
Apps to make Cabinet Vision work for you.

## **Oversize Small Parts for CNC - What's Included**

System Parameters that show in Job Notes...

- 1. Minimum Cut Size (DX)
- 2. Minimum Cut Size (DY)

Job Properties		?	×
	Information Comment Schedule Notes Parameters		
Job	ucs-Minimum Cut Size (DX) 120		
	ucs-Minimum Cut Size (DY) 120		



The UCS included in the package re-sizes small parts to meet your minimum sizes on the CNC. It also adds a comment to your part so after it's edge banded, the factory guys know what the finished size is.

Automated Part Comment - Shown here on the part label...

Apps to make Cabinet Vision work for you.

## **Oversize Small Parts for CNC - What's Included**

Part No:1 Sheet No:1	Cab #			
Bob Black - 153 Firth Street - (Bathroom 2)				
Filler				
Material: Colour A 18mm				
Edging: E - 2mm Col A Band ਯੂ ਰੋ	(Ē)			
<u>Program:</u>	<b>733</b> With Grain			
Finished Size (Width) = 50				
Program:	733 With Grain			

3 x 4 Part Label pictured here is not included in this package - Take a look at the Reports Category on the Joinery IT's CV App Store